

Annexure- D

BUILDING SAFETY CERTIFICATE

No 156/गं.अ.वि.0/प्रमाणपत्र/2025-26

Dated 29.09.25

It is certified that the existing building Ishan Public School (name of the building or premises) at Shukulpur, Sangipur Pratapgash (V.P.) 230139 (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+1	—	—	—	—	—

The building is owned/occupied by Ishan Public School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of R.E.S. Pratapgash (Name of Department/ Govt) on 29.09.25 (date of inspection) in the presence of Prashant Kumar Shukla President Ishan P.S. (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 29.09.25 for a period of 05 years in accordance with rule and subject to compliance of the specific conditions as appended

- 1 Proper Maintenance of building.
- 2 Proper Maintenance of drainage system.
- 3 Proper Maintenance of terrace.
- 4 Proper Maintenance of roofs.

Issued on 29.09.25 at 2:30 PM. by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.



Signature with Seal

Kishan Medaniwal 29/09/25

Name KISHAN MEDANIWAL

Designation R.E.S.

Name & Address of Department Office